

Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of October 11th, 2021



Inside the main entrance standing on the historic gym floor, looking south. Guardrail is installed on level 3. The historic gym floor on level 2 is being sanded. The concrete floors on level 1 are being polished.




View of the historic gym floor from above looking towards the main entrance on the north side of the building. The sanding of the floor has begun along the north side.



Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of October 11th, 2021



On level 1 the floors are being polished. Last week the team polished the west side. This week they moved over to the east side. Aluminum doors and frames continue to go in as well. Check it out!

The steel canopy between the Main Library and the Bear Down Gym will finish up this week. Underneath, the landscaping has begun with winding pathways, concrete benches, and new plants.

