



# Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of November 22nd, 2021



*Inside the main entrance standing on the historic gym floor, looking south. Final touches are finishing up on level 3. Message boards are being installed on level 2 and bathroom accessories are being installed in the level 1 cabanas.*



*View of the level 1 reception area. Carpet is being installed in front of the desk. The 'A' from the historic gym floor has been hung on the hallway to the Community Clubhouse beyond.*

# Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of November 22nd, 2021



*Pavers have been installed on the northeast corner of the building. The landscape lighting has gone in as well. Check out the new light posts!*

*The flooring and ceilings have been completed in the level 1 Wellness Studio. This open space is filled with natural light coming from the restored exterior windows!*

