


Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of August 30th, 2021



Inside the main entrance standing on the historic gym floor, looking south. Lighting fixtures are going in on level 3, acoustical ceilings are finishing up on level 2, and the catering kitchen is being framed on level 1.




On level 3, light fixtures have been installed in the corridors and conference rooms! The concrete floors on level 3 are also being polished this week.




Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of August 30th, 2021



On the left, the exterior receives concrete patch work around two new louvers for the mechanical system. On the right, the precast stair treads are continuing to be installed!



Millwork install is ongoing up on level 3! This area is set behind the level 3 reception desk.

