



# Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of April 12, 2021




*Inside the main entrance standing on the historic gym floor, looking south. Picture was taken just prior to the Level 2 concrete deck placement.*



*East side of the Level 3 deck. Mechanical team is installing the ductwork above the structural steel. Framing and rough-in will begin following the completion of overhead mechanical systems.*

## Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of April 12, 2021



*View of the existing bleachers above the protected historic gym floor. The main entrance is off to the right with the new structural steel on the far left.*

*Diagonal braces in the background support the exterior walls while the existing floors inside were removed and replaced with the new structural steel and concrete decks.*

*Metal framing is staged outside the building prior to installation on level 3. The Main Library is visible on the left and the new Bartlett Academic Success Center is beyond.*

